



HIGH PERFORMANCE PROTECTIVE BOILERSUIT

Chemmaster suits are tough and uncompromising, with exceptional chemical resistant properties against many acids and alkalis.

FEATURES

- ▶ Tough, high tear and abrasion resistant Green PVC
- ▶ Re-usable
- ▶ Excellent chemical resistance against many acids and alkalis
- ▶ Stitched and high frequency welded seams for added protection
- ▶ Available in a wide range of stock options to suit the wearer and work process
- ▶ Be-spoke Chemcre8 options available to order
- ▶ Proven chemical protection solution for over 30 years
- ▶ Available in a wide range of sizes with special sizes available to order



ORDERING INFORMATION

Part Number:

- | | |
|-----------------|--|
| CMBC | - Chemmaster boilersuit with collar S-XL |
| CMBC-EW | - As CMBC with elasticated wrists S-XL |
| CMBH | - Chemmaster boilersuit with hood S-XXXL |
| CMBH-EW | - As CMBH with elasticated wrists S-XXL |
| CMBH-EWA | - As CMBH with elasticated wrists and ankles |

SUITABLE APPLICATIONS

Recommended applications include:

- Oil & Gas
- Shipping
- Chemical site handling
- Tank cleaning
- Chemical cleaning
- Petrochem refining
- Heavy industry
- Chemical road freight



TECHNICAL SPECIFICATIONS

OPTIONS

PRODUCT	PRODUCT OPTIONS				CODE
	Collar	Hood	Elasticated Wrists	Elasticated Wrists and Ankles	
Boilersuit	✓				CMBC
	✓		✓		CMBC-EW
		✓			CMBH
		✓	✓		CMBH-EW
		✓	✓	✓	CMBH-EWA

SIZING

The following table reflects the dimensions of the four standard sizes. We also manufacture sizes outside the standard sizes, eg XS, XXL, XXXL etc. We also provide customers with the facility to order garments with dimensions to their own bespoke size.

SIZE	CHEST GIRTH (cm)	BODY HEIGHT (cm)
S	90 - 98	162 - 168
M	98 - 106	168 - 174
L	106 - 114	174 - 180
XL	114 - 122	180 - 186

CERTIFICATION



STORAGE AND MAINTENANCE

It is recommended that new Chemmaster garments are stored in their original packaging and clear of UV sources. Following use, and after being been RINSED DOWN and DRIED, Chemmaster clothing should be stored in a cool, dry and clean environment.

It is recommended that the wash care instructions, as detailed on the care label, are followed. After use, to remove contamination, Chemmaster clothing should be RINSED DOWN with cold water, and subsequently, allowed it Drip Line Dry, in the shade, clear of UV sources. Advice: For reasons of hygiene the garments should preferably be worn by the same person